<u>Description</u> - One story brick and stone building. Brick front; quarried schist walls, from nearby rock exposures. Limestone flagging was used. Dentils under cornice on front facade; brackets on side. Narrow iron doors.

References - Weston, Mother Lode Album, 1948, p. 10, 5 photos. Geologic Guidebook, 1948, p. 99

Author of Card - H. E. Rensch, Hist., 2225 W. Capitol Avenue, West Sacramento, California September 1961